

## CORRIGENDUM

### Page 18

*Au paragraphe 8.1, au lieu de:*

8.1 Les douilles doivent être munies de l'un des moyens de connexion suivants:

- bornes à serrage sous tête de vis;
- bornes sans vis du type à ressort ou en forme de coin;

*lire:*

8.1 Les douilles doivent être munies d'au moins un des moyens de connexion suivants:

- bornes à vis;
- bornes sans vis;

### Page 20

*Au paragraphe 8.2, au lieu de:*

- Les bornes à serrage sous tête de vis doivent être conformes à la section quatorze de la CEI 598-1.
- Les bornes sans vis du type à ressort ou en forme de coin doivent être conformes à la section quinze de la CEI 598-1.

*lire:*

- Les bornes à vis doivent être conformes à la section quatorze de la CEI 598-1.
- Les bornes sans vis doivent être conformes à la section quinze de la CEI 598-1.

### Page 19

*Subclause 8.1, instead of:*

8.1 Lampholders shall be provided with one of the following means of connection:

- terminals with screw clamping;
- screwless terminals of spring or wedge type;

*read:*

8.1 Lampholders shall be provided with at least one of the following means of connection:

- screw type terminals;
- screwless terminals;

### Page 21

*Subclause 8.2, instead of:*

- Terminal with screw clamping shall comply with Section Fourteen of IEC 598-1.
- Screwless terminals of spring or wedge shall comply with Section Fifteen of IEC 598-1.

*read:*

- Screw type terminals shall comply with Section Fourteen of IEC 598-1.
- Screwless terminals shall comply with Section Fifteen of IEC 598-1.