



Shipbuilding — Magnetic compasses, binnacles and azimuth reading devices — Class B

TECHNICAL CORRIGENDUM 1

Construction navale — Compas magnétiques, habitacles et alidades — Classe B

RECTIFICATIF TECHNIQUE 1

Technical corrigendum 1 to International Standard ISO 613: 1982 was prepared by Technical Committee ISO/TC 8, *Shipbuilding and marine structures*, Sub-Committee SC 18, *Navigational instruments and systems*.

Various clause and subclause references in the text of ISO 613 : 1982 are wrong: make the changes indicated in the following table.

Clause No.	Line	Wrong reference	To be amended to:
6.4.2	4	6.5	6.2
6.6.3	3	6.9.2	6.6.2
6.7.2	6	6.6.2	6.3.2
6.7.2	6	6.9.1	6.6.1
6.7.2	7	6.9.2	6.6.2
6.7.2	7	6.9.3	6.6.3
6.7.2	8	6.9.5	6.6.5
7.4	3	6.7.2	6.4.2
9	3	6.5	6.2
9	3	6.6.2	6.3.2
9	3	6.7	6.4
9.2	3	6.9.2	6.6.2