

SAE The Engineering
Resource For
Advancing Mobility

400 COMMONWEALTH DRIVE, WARRENDALE, PA 15096

AEROSPACE
MATERIAL
SPECIFICATION

AMS 2646C
Superseding AMS 2646B

Issued 3-1-55
Revised 4-1-82

CONTRAST DYE PENETRANT INSPECTION

1. SCOPE:

- 1.1 Purpose: This specification establishes a procedure for detection of discontinuities open to the surface of parts by the use of a penetrating dye.
- 1.2 Application: Detection of discontinuities such as cracks, laps, porosity, cold shuts, lack of bond, and similar defects. Because inspection can be performed in normal light, this method can be used under conditions where use of fluorescent penetrant inspection is impracticable.

2. APPLICABLE DOCUMENTS: None.

3. TECHNICAL REQUIREMENTS:

3.1 Materials:

- 3.1.1 Penetrant: Shall be a strongly-colored liquid capable of penetrating fine discontinuities. The penetrant shall be removable by washing with water or with other common solvents, or by vapor degreasing; penetrant shall be noncorrosive.
- 3.1.2 Developer: The developer shall be of the type recommended by the manufacturer of the penetrant used.
- 3.1.3 Liquid vehicles of the penetrant and developer shall be noninjurious to the parts to be tested.
- 3.1.4 Check of Penetrant: The dye penetrant materials shall be checked for effectiveness as often as necessary to maintain proper control.

SAE Technical Board rules provide that: "All technical reports, including standards approved and practices recommended, are advisory only. Their use by anyone engaged in industry or trade or their use by governmental agencies is entirely voluntary. There is no agreement to adhere to any SAE standard or recommended practice, and no commitment to conform to or be guided by any technical report. In formulating and approving technical reports, the Board and its Committees will not investigate or consider patents which may apply to the subject matter. Prospective users of the report are responsible for protecting themselves against liability for infringement of patents."

AMS 2646C

3.2 Equipment: For permanent installations where materials are applied by immersion of parts, equipment shall be so constructed and arranged as to permit uniform, controlled operation.

3.3 Preparation of Parts:

3.3.1 Parts shall normally be contrast dye penetrant inspected prior to all surface treatments such as plating, anodizing, dichromating, peening, or similar treatments which would tend to close or mask surface discontinuities. Contrast dye penetrant inspection may be performed after surface treatments provided it is demonstrated that the treatment is of such a nature that discontinuities are not obscured. This section shall not be interpreted as prohibiting additional dye penetrant inspection after processing or after use of parts.

3.3.2 If machined surfaces are to be inspected, they shall be finished with a clean cut to prevent flowing or burnishing of the surface layer or shall be etched with a suitable etchant to remove flowed or burnished layers which might mask discontinuities. Parts shall not be etched indiscriminately because etching itself tends to mask surface discontinuities.

3.3.3 All parts shall be cleaned and dried in such a manner as to leave the surfaces free from grease, oil, soaps, alkalies, and other substances which would interfere with inspection. Vapor degreasing is generally suitable for this purpose.

3.4 Procedure: After preparation, the parts shall immediately be subjected to the following operations:

3.4.1 The parts shall be immersed in the penetrant, or shall be sprayed or brushed with the penetrant, and shall be allowed to remain immersed in the penetrant or to stand for a sufficient length of time to allow satisfactory penetration into all discontinuities. This time shall be not less than 5 minutes. The time of immersion or standing will depend upon the character and fineness of the discontinuities, the effectiveness of penetration increasing with time.

3.4.2 Parts shall be removed from the penetrant and cleaned thoroughly using a medium which will remove penetrant from the surfaces of parts; washing with water shall be used when the penetrant is water washable. When other than water washable penetrants are used, the penetrant shall be removed with a suitable cleaner. Excessive cleaning which would remove the penetrant from discontinuities shall be avoided.

- 3.4.3 The parts shall be dried as thoroughly as possible. Drying of parts may be accomplished by evaporation at room temperature or by placing the parts in a circulating warm air oven or in the air stream of a hot air dryer. Excessive drying time or temperature above 75°C (165°F) should be avoided to prevent excessive evaporation of the penetrant. If heat is used for drying parts, parts shall be cooled to approximately 50°C (120°F) before proceeding to the operation of 3.4.4.
- 3.4.4 The developer shall be applied to the dry parts as lightly and as evenly as possible. Wet developer shall be thoroughly mixed by agitation immediately prior to its application. After the developer has been applied, care shall be taken that no indication is disturbed or obliterated in subsequent handling.
- 3.4.5 After sufficient time (not less than 10 min.) has been allowed to develop indications, parts shall be examined for indications of discontinuities open to the surface.
- 3.4.6 The parts shall be cleaned following the inspection to remove penetrant and developer.

4. QUALITY ASSURANCE PROVISIONS:

4.1 Disposition:

- 4.1.1 Interpretation of the indications revealed by this inspection procedure and final disposition of the parts shall be the responsibility of only qualified personnel having experience with contrast dry penetrant inspection. Procedure for qualification of personnel shall be acceptable to purchaser.
- 4.1.2 Parts having discontinuities considered detrimental to strength or serviceability shall be rejected.
- 4.1.3 Parts containing minor discontinuities not considered detrimental to the part under operating conditions may be approved for acceptance without remedial operations at the discretion of authorized personnel.
- 4.1.4 Parts containing discontinuities of such nature and location that their removal would not adversely affect the serviceability of the part, although local sections might be outside drawing limits, may have such discontinuities removed with the approval of authorized personnel after due consideration of the stress distribution within the part together with the function of the part itself. If a discontinuity is removed, the spot shall be blended in such a manner as to minimize surface flow of the material and reinspected. Swab etching of the blended area before reinspection is recommended wherever practicable. Etched surface shall be polished after reinspection.

AMS 2646C

- 4.2 Responsibility for Inspection: The inspection source shall be responsible for performing all required tests and identifying the parts tested and accepted as required by 5.1 or for providing reports of tests as required by 4.4. Purchaser reserves the right to sample and to perform any confirmatory testing deemed necessary to ensure conformance to the requirements of this specification.
- 4.3 Sampling: Shall be as agreed upon by purchaser and the inspection source.
- 4.4 Reports: If marking or dyeing as in 5.1 is impracticable, or when permitted by purchaser in lieu of marking or dyeing, vendor shall report on an appropriate form the penetrant and developer used and the number of pieces tested in each lot. The report shall also include a statement that all parts in the shipment conform to the standards specified by the purchaser.
5. PREPARATION FOR DELIVERY:
- 5.1 Identification: Parts which have satisfactorily passed the contrast dye penetrant inspection described herein shall be identified as follows:
- 5.1.1 Wherever practicable, the character "P" shall be legibly marked, by etching or impression stamping, on all parts actually inspected including those parts from a lot accepted on a sampling basis.
- 5.1.2 Parts accepted on a sampling basis but not actually inspected may be identified by the "P" character enclosed in a circle.
- 5.1.3 Where impression stamping or etching is not appropriate because of size, finish, or function of the part, identification may be by dyeing, unless parts are dyed for other reasons, or by tagging; when dyeing is used, a blue dye shall be used on all parts actually inspected and an orange dye on parts accepted on a sampling basis but not actually inspected.
- 5.1.4 Fastener items and parts which are not individually marked shall be packaged and the package marked to indicate conformance, unless otherwise specified.
- 5.1.5 The markings shall have no deleterious effect on the parts or their performance and shall be sufficiently stable to withstand normal handling.
- 5.2 Protective Treatment: All parts susceptible to corrosion shall be coated with a corrosion inhibiting oil.
6. ACKNOWLEDGMENT: A vendor shall mention this specification number and its revision letter in all quotations and when acknowledging purchase orders.
7. REJECTIONS: Parts not inspected in accordance with this specification or modification authorized by purchaser shall be rejected.