

Connector Accessories, Electrical, Backshell, 90°, Self-locking, Shield Band Termination (RFI/EMI), Shrink Sleeve Accommodation, Category 3B (For MIL-DTL-5015 Crimp, MIL-DTL-26482 Series 2, AS81703 Series 3 and MIL-DTL-83723 Series III Connectors)

This amendment forms a part of AS85049/84A Dated 2007-06

1). Present Requirement: (Sheet 1)

The requirements for procuring the product described herein shall consist of this specification sheet and the latest issue of: SAE AS85049.

Change Requirement: (Sheet 1)

NOTICE

The requirements for procuring the product described herein shall consist of this specification sheet and the latest issue of SAE AS85049.

Rationale for Change: Up-dated the procurement statement to comply with SAE guidelines.

2). Present Requirement: (Table 1, Sheet 3)

A Max Dia for shell size 08 reads: .855

Change Requirement: (Table 1, Sheet 3)

A Max Dia for shell size 08 is: .885

Rationale: Type-o error, A Max Dia: same requirement as defined on AS85049/82.

SAE Technical Standards Board Rules provide that: "This report is published by SAE to advance the state of technical and engineering sciences. The use of this report is entirely voluntary, and its applicability and suitability for any particular use, including any patent infringement arising therefrom, is the sole responsibility of the user."

SAE reviews each technical report at least every five years at which time it may be reaffirmed, revised, or cancelled. SAE invites your written comments and suggestions.

Copyright © 2010 SAE International

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior written permission of SAE.

TO PLACE A DOCUMENT ORDER: Tel: 877-606-7323 (inside USA and Canada)
Tel: +1 724-776-4970 (outside USA)
Fax: 724-776-0790
Email: CustomerService@sae.org
http://www.sae.org

SAE WEB ADDRESS:

**SAE values your input. To provide feedback
on this Technical Report, please visit
http://www.sae.org/technical/standards/AS85049/84A_A1**