

Publication 439-1 de la CEI
(Troisième édition - 1992)

Ensembles d'appareillage
à basse tension

Partie 1: Ensembles de série et
ensembles dérivés de série

IEC Publication 439-1
(Third edition - 1992)

Low-voltage switchgear and
controlgear assemblies

Part 1: Type-tested and
partially type-tested assemblies

CORRIGENDUM

Page 10

Après CEI 50, introduire «CEI 60, Techniques des essais à haute tension».

Page 36

4.3

A la deuxième ligne, supprimer «admissible» après «durée».

Page 52

7.1.2.3.5 a)

A la deuxième ligne, changer «7.1.2.3.3» en «7.1.2.3.4».

Page 110

8.1.1 d)

Changer «la continuité» en «l'efficacité».

8.1.2

Ne concerne que le texte anglais.

Page 114

Tableau 7 n° 4

Remplacer «Continuité électrique ... » par «Efficacité» ... »

Page 122

Tableau 9

Les notes doivent être attribuées aux têtes de colonnes selon ci-dessous:

- Domaine du courant d'essai¹
- Barre de cuivre²
- Section³
- Dimensions³

Page 11

Insert after IEC 50 "IEC 60, High-voltage test techniques".

Page 37

4.3

Delete "withstand" after "short-time" in the second line.

Page 53

7.1.2.3.5 a)

Change "7.1.2.3.3" to "7.1.2.3.4" in the second line.

Page 111

8.1.1 d)

Instead of "continuity" read "effectiveness".

8.1.2

The second sentence shall read: "They are carried out on every new ASSEMBLY after its assembly ...".

Page 115

Table 7 No. 4

Concerns the French text only.

Page 123

Table 9

The notes shall be referred to in the column headings as follows:

- Range of test current¹
- Copper bars²
- Cross-section³
- Dimensions³